



ASM-020

SERVICE BULLETIN ASM-020

Product: Antenna Systems Monitor

Subject: Firmware 2.81 Release

Date: 15th May 2017

Description

This Service Bulletin announces the release of baseline 2.81 firmware for the Antenna System Monitor (ASM) series products.

The version 2.81 firmware update file ("FFP") is available for download from the RFI website http://www.rfiwireless.com.au/multicoupling-monitoring/monitoring/antenna-system-monitor-asm3852.html#tab_downloads, and may be flashed into existing ASM models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

Product Enhancement

The version 2.81 firmware addresses the issue;

- i) Tx Coupler Calibration values entered may change during the Tx Port(s) Calibration process

During the Tx Port Calibration process, the coupler value entered into the Calibration Tx Port(s) GUI page may change during the transition to and from the Channel Diagnostics GUI page. Revision 2.81 addresses this issue.

Upgrading to Firmware 2.81

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your ASM prior to commencing an upgrade to this version 2.81 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your ASM.

The required intermediate firmware version transitions are;

- Firmware below version 2.0 must transition through version 2.0 or 2.05 prior to attempting an update to 2.1 or above.
- Firmware below 2.60 must transition through version 2.60 prior to attempting an update to 2.70 or above.

Cost Impact

Firmware version 2.81 is available to RFI customers at no charge.

- END -