

SERVICE BULLETIN ASM-024

Product: Antenna System Monitor

Subject: Firmware 2.85 Release

Date: 17th February 2021

Description

This Service Bulletin announces the release of baseline 2.85 firmware for the Antenna System Monitor (ASM) series products.

The version 2.85 firmware update file (“FFP”) is available for download from the RFI website https://www.rfiwireless.com.au/multicoupling-monitoring/monitoring/antenna-system-monitor-asm3852.html#tab_downloads, and may be flashed into existing ASM models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

Product Enhancement

This version 2.85 firmware provides enhanced SNMP functionality including SNMP v1 support, additional northbound Traps and southbound GET commands support.

Refer to *Service Bulletin – ASM SNMP* for further information on these new features.

Upgrading to Firmware 2.85

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your ASM prior to commencing an upgrade to this version 2.85 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your ASM.

The required intermediate firmware version transitions are;

- Firmware below version 2.0 must transition through version 2.0 or 2.05 prior to attempting an update to 2.1 or above.
- Firmware below 2.60 must transition through version 2.60 prior to attempting an update to 2.70 or above.

Cost Impact

Firmware version 2.85 is available to RFI customers at no charge.