

SERVICE BULLETIN – ASM-027

Product: Antenna System Monitor

Subject: Firmware 2.88 Release

Date: 23rd June 2023

Description

This Service Bulletin announces the release of baseline 2.88 firmware for the Antenna System Monitor (ASM) series products.

The version 2.88 firmware update file (“FFP”) is available for download from the RFI website <http://www.rfi.com.au>, and may be flashed into existing ASM models by following the Maintenance – Firmware Update process in the Graphical User Interface (GUI) or User Manual.

Product Enhancement

- i) Response time for Ethernet packet processing is improved in-order to reduce the frequency of SNMP packet timeouts.

Upgrading to Firmware 2.88

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your ASM prior to commencing an upgrade to this version 2.88 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your ASM.

The required intermediate firmware version transitions are;

- Firmware below version 2.0 must transition through version 2.0 or 2.05 prior to attempting an update to 2.1 or above.
- Firmware below 2.60 must transition through version 2.60 prior to attempting an update to 2.70 or above.

Cost Impact

Firmware version 2.88 is available to RFI customers at no charge.

-END-