SERVICE BULLETIN RMC-012

Product: Receiver Multicoupler

Subject: Firmware 1.70 Release   **Date: 16th September 2019**

Description

This Service Bulletin announces the release of baseline 1.70 firmware for the Receiver Multicoupler (RMC) series products.

The version 1.70 firmware update file ("FPP") is available for download from the RFI website, and it may be flashed into existing RMC models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

Product Enhancements

The version 1.70 firmware supports a manufacturing design change that took effect on the 16th September 2019 and applies to all RMC products shipped after this date. No new features were introduced with this revision. Version 1.70 is fully compatible with all earlier production units.

Upgrading to Firmware 1.70

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your RMC/TTA prior to commencing an upgrade to this version 1.70 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your RMC/TTA.

Automated firmware upgrades, the retrieval of currently installed firmware versions, site names, model numbers, serial numbers, and the testing of communications connectivity to a fleet of RMC/TTAs can be managed and actioned using the RFI Uploader software package.

Cost Impact

Firmware version 1.70 is available to RFI customers at no charge.

- END -